

NEXTSTEP for Intel Processors Release 3.3

SCSI Driver Overview

Driver: Adaptec 154x family and compatible

Driver Overview: NeXTanswer #1758

Last Update: March 25, 1996

Availability Information

A version of this driver is on the CDROM

Newer Released Driver in NeXTanswers: No, Version 0.00, as NeXTanswer #

Newer Beta Driver in NeXTanswers: No, Version 0.00, as NeXTanswer #

Driver Name / Installer .pkg: Adaptec1542B

Driver Type: SCSI

Driver Scope: Product Family

Supported Components: Adaptec AIC-6251, Adaptec AIC-7970

PC Bus / Interface Supported by Driver*: EISA, ISA

General Overview notes: The Adaptec154x compatible driver is designed to support a variety of SCSI adapters from Adaptec and several third parties.

Supported Products / Add-on Adapters:

Adaptec 154xB (ISA)

Adaptec 154xC (ISA)

Adaptec 154xCF (ISA)

Adaptec 174x (EISA) in standard 154x mode only

Supported Products / Systems (ie integrated into PC System):

Special Features of Driver / Driver Notes:

The onboard floppy controller, available on the 1542 cards, is not supported.

SCSI Driver Details

Supported Connectors: 50-pin Centronics (Standard SCSI), 50-pin Header (Internal SCSI), 50-pin High Density (SCSI-2)

Access Mode: DMA

Attributes*: SCSI-2

Cache Size Supported*: N/A

Known Problems

- For setup and installation of the 154xB see NeXTanswers document number 1107.
- For setup and installation of the 154xC/CF see NeXTanswers document number 1108.
- NEXTSTEP does not officially support the floppy controller integrated into the 1542B. Use the floppy controller integrated into your system's motherboard.
- When installing NEXTSTEP onto an IDE hard disk drive, the CD-ROM drive's SCSI ID number should be zero.
- Some users have reported problems during the installation process if the CD-ROM drive's SCSI ID number is set to zero. NEXTSTEP will freeze after displaying the message rootdev 608 when this problem is encountered. Setting the CD-ROM drive's SCSI ID to six has fixed the problem when nothing else seemed to work.
- Improper SCSI termination can cause strange, unreproducible errors. Be certain that the first and last devices on the SCSI bus (and only these two devices) are terminated. For more information on this topic, see NeXTanswers document number 1109_SCSI_Setup.
- Avoid system configurations combining an Adaptec 154xB/C/CF and an ATI Ultra Pro EISA card. A hardware conflict exists which causes data corruption on SCSI hard disks.

- If your system includes an Adaptec 1542B and you do not have jumper six enabled it will hang. It will boot off the floppy and recognize the SCSI drives, but instead of starting the install process, it will hang with the messages:

fdisk: bogus bios info
some bios' can't handle non-sequential targets.

- The Adaptec 1542B does not support 2.88MB floppy drives attached as SCSI devices.
- See also NeXTanswers document number 1541_Adaptec_Driver_Related_Problems.rtf. Adaptec, Inc. <http://www.adaptec.com/>

Driver Version Notes

Future Planning

Future / Update Planning:

Reason for New Driver / Update:

New Driver / Update Timeframe:

New Driver / Update Description:

Note: Information contained in the "Future Planning" section of this document does not constitute a commitment on the part of NeXT to complete the planned development work.

* - Indicates information that is inclusive of the entire capability of this driver. Not all devices supported by this driver may include all features listed. Check any available NeXTanswers and the hardware manual for the device for additional information.

Product Vendor

Adaptec Inc.

691 South Milpitas Blvd.
Milpitas, CA 95035
USA

+1 (408) 945 8600 international phone number
+1 (800) 959 7274 USA toll-free (customer support) phone
+1 (408) 945 7727 bulletin board system
+1 (408) 957 7150 faxback system
+1 (408) 262 2533 fax
WWW: <http://www.adaptec.com/>