

#### Notes on TwinTurbo™ Control Panel:

This Control Panel requires the new Display Library which is part of System 7.5.3 and is a separate file on older system. If you encounter the problem of the board not preserving the resolution after reboot you may want to upgrade your system to 7.5.3. This can be done by installing the new system or by upgrading 7.5 with System Enabler 2.0.

#### Notes on TwinTurbo™ Software 4.0.2:

This version fixes the following bugs:

1. FileMaker Pro text problem.
2. CorelDraw6 text problem
3. BBEdit text problem

#### Notes on TwinTurbo™ Software 4.0.2b1:

This version fixes the following bugs:

1. It works with UMAX S900 machines in all slots now.
2. QuickTimeVR works correctly now.

#### Notes on TwinTurbo™ Software 4.0.1:

This version fixes the compatibility problem that it had with certain CPU's. It also allows multiple IMS boards in the system now. These are the know bugs:

1. The accelerator doesn't work with UMAX S900 machines when the board is in the bottom four slots. Moving the board to either of the top two slots will fix the problem.
2. QuickTimeVR may not work correctly on 9500MP running multiprocessor system software.

#### Notes on TwinTurbo™ Software 4.0:

This version significantly improves the acceleration over 3.8. It also fixes the QuickTime acceleration problem that hows up on recording.

#### Notes on TwinTurbo™ Software 3.8:

This version fixes the Umlaut-A problem. The character was not showing up in previous version. It also fixes the background repaint problem that somtimes appears in M2 boards.

#### Notes on TwinTurbo™ Software 3.6:

This version fixes the text hilite problem and resolves the conflict with some applications such as Photoshop that sometimes leads to type 11 error.

#### Notes on TwinTurbo™ Software 3.5:

This version adds support for the new MP2 and MV2 boards. It also

adds an MPEG hardware scaler.

Notes on TwinTurbo™ Upgrade version 3.1:

1. This upgrade applies to Twin Turbo™ 128M and Twin Turbo™ 128M2 boards only.
2. This version fixes the bug that causes LocalTalk to freeze when copying large files.
3. If you have version 2.1 ROM or less with this upgrade, you would be able to access all the resolutions the board supports, up to 1920x1080. Just plug the monitor into the VGA connector and leave the Mac connector open. It should come up with default resolution or the resolution from last boot. The default resolution is 640x480x60Hz for version 2.1 or 2.0 ROM and 832x624x75Hz for version 1.x ROM plus the upgrade.

To force the system to the default resolution, follow the following procedure:

- Reboot and hold down command-option-p-r.
- Wait till the system restarts. Release the keys and hold down shift key.
- Release the key after the "Welcome to Macintosh. Extensions Off." message shows up.
- The system should be in default mode.

Notes on TwinTurbo™ 128M8:

- The resolution 1920x1080 Millions mode is not supported at 72Hz.
- It is recommended that the system has at least 32M of memory installed for maximum performance.