

NOTE: This Technical Note has been [retired](#). Please see the [Technical Notes](#) page for current documentation.

Technical Note DV12

Our Checksum Bounced

CONTENTS

[A Bit of History](#)

[Drivers That Check In, But Don't Check Out](#)

[Just When You Thought It Was Safe To Call _SysEnviron](#)

[To Sum it Up](#)

[References](#)

[Change History](#)

[Downloadables](#)

This Technical Note discusses a fix to a SCSI Manager bug that concerns all developers working with SCSI and NuBus device drivers.

Updated: [October 01 1989]

A Bit of History

The boot code contained in the ROM has a feature used by the Start Manager to perform a checksum on the SCSI driver being loaded. *Inside Macintosh*, Volume V-573, The SCSI Manager, documents this being performed on the Macintosh SE and later models for volumes using the new partitioning method. The truth, however, is that checksum verification was never performed due to a bug in the ROM, and because of this, all drivers loaded regardless of validity.

That was the case until recently. On new Macintosh computers, the checksum verification works. That's the good news: we've fixed the bug. Now the bad news: this fix causes a number of third-party SCSI drivers to fail to load.

Some SCSI drivers improperly implement the new partitioning scheme. If the partition map entry name begins with the four letters "Machi" (case sensitive) and is of type "Apple_Driver", the driver now has its checksum verified with the entries in the partition map. If this checksum fails, the driver is not loaded. This checksum algorithm is documented in *Inside Macintosh*, Volume V-580, The SCSI Manager.

Note:

[Inside Macintosh: Devices](#) fails to include the disk driver checksum algorithm. As it is now quite difficult to obtain copies of *Inside Macintosh*, Volume V, the algorithm is included below:

```

DoCksum
    moveq.l    #0,d0        ; initialize sum register
    moveq.l    #0,d7        ; zero extended byte
    bra.s      CkDecr       ; handle 0 bytes

CkLoop
    move.b     (a0)+,d7     ; get a byte
    add.w      d7,d0        ; add to checksum
    rol.w      #1,d0        ; and rotate

CkDecr
    dbra       d1,CkLoop    ; next byte
    tst.w      d0           ; convert a checksum of 0
    bne.s      @1          ; into $FFFF
    subq.w     #1,d0        ;

@1

```

The following is a C equivalent:

```

static UInt32 ChecksumDriver(void *start, UInt32 length)
{
    UInt8  *cursor;
    UInt32 result;

    cursor = (UInt8 *) start;
    result = 0;

    while ( length != 0 ) {
        result = result + *cursor;
        result = ((result << 1) & 0xFFFFE) |
                ((result >> 15) & 0x00001);
        cursor += 1;
        length -= 1;
    }
    if (result == 0) {
        result = 0xFFFF;
    }
    return result;
}

```

[Back to top](#)

Drivers That Check In, But Don't Check Out

The checksum routine tests the number of bytes specified in `pmBootSize`, beginning at the start of the driver boot code. Only drivers contained within the new partition map have this test performed. If you are using the old partition map scheme documented in *Inside Macintosh*, Volume IV-283, The SCSI Manager, the driver does not have its checksum validated. The following is the startup logic in the new Macintosh ROMs:

```

IF
    pmSig = $504D
AND
    pmPartName = Maci
AND
    pmPartType = Apple_Driver
AND
    pmBootChecksum = ChecksumDriver(bootCode, pmBootSize)
THEN
    Load the driver
ELSE
    Do not load the driver

```

[Back to top](#)

Just When You Thought It Was Safe To Call `_SysEnviron`s

The call `_SysEnviron`s was created for compatibility reasons. It allows an application to make a single call to the system to determine its characteristics. It keeps the application from reading ROM addresses and low memory. This trap is now in the ROM of new machines. But, before you get excited about this addition to ROM, there is something that *Inside Macintosh*, Volume V-5, Compatibility Guidelines, states that must be understood by those writing SCSI drivers:

"All of the Toolbox Managers must be initialized before calling SysEnviron.s." "...SysEnviron.s is not intended for use by device drivers, but can be called from desk accessories."

This statement means that neither SCSI nor NuBus device drivers can use `_SysEnviron`s. The earliest possible moment to call `_SysEnviron`s is at INIT time. Some SCSI drivers call `_SysEnviron`s, and this causes the Macintosh to crash at boot time.

[Back to top](#)

To Sum Up

Check if your partition map is of the version described in the SCSI Manager chapter of *Inside Macintosh*, Volume V, and contains the `pmPartName` and `pmPartType` as mentioned earlier in this Note. If it does, then verify that the `pmBootChecksum` is correct. If the checksum is not correct, the new Macintosh computers will not load your driver. The solution to this problem is to have a valid partition map entry in all cases and to expect the Start Manager to perform the checksum verification regardless of the `machineType`.

`_SysEnviron`s is not available until the system has been initialized.

[Back to top](#)

References

Inside Macintosh, Volume IV-283, The SCSI Manager

Inside Macintosh, Volume V-5, Compatibility Guidelines

Inside Macintosh, Volume V-573, The SCSI Manager

[Inside Macintosh: Devices, SCSI Manager](#)

[Inside Macintosh: Devices, SCSI Manager 4.3](#)

[Technote OV 16, "Gestalt and SysEnviron: A Never Ending Story"](#)

NuBus is a trademark of Texas Instruments, Inc.

[Back to top](#)

Change History

01-October-1988 Originally written.

01-October-1999 The Note now includes the driver checksum algorithm, otherwise only documented in *Inside Macintosh* , Volume V.

[Back to top](#)

Downloadables



Acrobat version of this Note (K)

[Download](#)

[Back to top](#)

Technical Notes by [Date](#) | [Number](#) | [Technology](#) | [Title](#)
[Developer Documentation](#) | [Technical Q&As](#) | [Development Kits](#) | [Sample Code](#)