



## Why the UniDisk 3.5 Does Not Auto-Boot on Older Machines

If you look carefully, you will notice that the older (][, ][+ and unenhanced Iie) Autostart Monitor will not boot any SmartPort device because the ID byte at \$Cn07 = \$00 instead of \$3C (like the old Disk II). If Apple had left the ID bytes the same as the Disk II, then older versions of Apple II Pascal (1.2 and earlier) would assume that the drive was a Disk II.

## Where This Leaves You

The enhanced Iie ROMs, as well as the UniDisk 3.5 Iic ROMs and later (which you have if you are using a UniDisk 3.5 on a Iic) check only the first three ID bytes. This check means that they will not only auto-boot the UniDisk 3.5, but any SmartPort or ProDOS block device. On an older machine, you can boot one of these devices by typing PR#n from AppleSoft or Cn00G from the Monitor.

## Further Reference

---

- *Apple IIGS Firmware Reference*