NEXTSTEP for Intel Processors

Title: ALR Evolution IV Entry Number: 1363 Last Updated: <<Date June 13 1995>>

Product Vendor:

Advanced Logic Research, Inc.

9401 Jeronimo Irvine, CA 92718-1912 USA

+1 (800) 257 1230 USA toll-free phone +1 (800) 581 3332 faxback system +1 (714) 458 6834 bulletin board system (USA) +1 (416) 940 3460 bulletin board system (Canada) 011 44 635 550 208 bulletin board system (U.K.) WWW: http://www.alr.com/

Keywords: ALR, Evolution IV

Usage Commentary

The ALR Evolution IV provides proprietary ALR, EISA, and VESA Localbus expansion slots. These

expansion slots can be filled with either the ALR Tri-Combo card or other supported display adapters to provide a variety of grayscale or color video capabilities. The Tri-Combo card combines an ATI Mach-32 video chipset with an ALR cache memory card and NE2100 compatible Ethernet card. The ethernet capabilities of the ALR Tri-Combo are not currently supported under NEXTSTEP.

ALR Tri-Combo Video Support

Update 1 of the ATI display adapter device driver is provided in Release 3.2. This updated driver provides enhanced functionality for the ALR Tri-Combo's integrated video hardware. Anyone using Release 3.1 can get the updated driver from NeXTanswers via anonymous FTP (**ftp.next.com**) or electronic mail (**nextanswers@next.com**). Request document numbers 1341, **"1341_ATIDriver.pkg.compressed**," and 1340, **"1340_ATIDriverReadMe.rtf**."

Supported Video Modes

VRAM	8-bit Grayscale	16-bit Color
1MB	800 x 600 @ 60 or 72 Hz	800 x 600 @ 60 Hz
1MB	1024 x 768 @ 60, 72, or 76 Hz	_
2MB	1120 x 832 @ 60 or 68 Hz	1024 x 768 @ 60 or 76 Hz
2MB	1280 x 1024 @ 60 Hz	1120 x 832 @ 60 or 68 Hz (1)

(1) 1120 x 832, 16-bit color is supported only by adapters with the Mach32 68800-6 or XL graphics controllers. If you see periodic video "noise" along the left or right side of the screen when you select this display mode, then the adapter almost certainly has the older Mach32 chip and therefore doesn't support 1120 x 832 color.

For more information on the ATI Mach-32 chipset, see NeXTanswer #1122, "1122_ATI_Ultra_Pro.rtfd."

Setup and Installation

If you're using an ALR Tri-Combo card, use System Setup to disable the integrated ethernet capabilities. To access the System Setup Screens, press <Ctrl><Alt><Esc> while the system startup screen is displayed. Then press the <Page Down> key to go to the fourth screen. Finally, set "Lan Enable" to "Disable." The Lan Enable setting is not configured from the EISA Configuration Utility (ECU).

The following ECU settings were recorded by NeXT from an ALR Evolution IV known to have successfully installed and run NEXTSTEP Releases 3.1 and 3.2 for Intel Processors. The system was running off of a SCSI hard disk with a DPT 2022 SCSI controller.

EISA Configuration Utility Setup

System - Evolution IV/e System Board
System Board Peripherals
Embedded Hard Disk Controller Disabled
Floppy Controller Enabled
Parallel Port LPT1
Serial Port 1 COM1
Serial Port 2 COM2
Embedded Mouse Enabled
Floppy Disk Drives
Disk A: 1.44 ME
Disk B: Not Installed
Hard Disk Drives
Disk C: Not Installed
Disk D: Not Installed
Base Memory KB
Extended Memory 48128 KB
Maximum Memory Limit No Limit
Motherboard BIOS Shadow Enabled
Video BIOS Shadow Disabled
System Speed Fast
AT Hard Disk Transfer Mode PIO
AT Hard Disk Parameters Translate
CPU Clock Speed
Display Monitor EGA/VGA
Coprocessor
DPT - DPT SCSI Host Adapter (PM2X22A/9X)

CONTROLLER PARAMETERS WD1003 Boot Address Interrupt Number Floppy Disk Controller SCSI BIOS ROM Address Host Bus Adapter SCSI ID	15 Edge Disabled Enabled at C8000h
SCSI PARAMETERS Maximum Transfer Rate External Cable Detection SCSI Termination Command Queuing Command Timeout	Enabled - 5MB/s Enabled Enabled **
CACHE PARAMETERS Cache	50% 30% Enabled Disabled
!DPTA410.CFG Version	006A

- * To achieve 10MB/second transfer, you must have very good cabling and termination.
- ** Some SCSI devices don't implement Command Queuing correctly and require that you disable this feature.
- *** See the note in NeXTanswer #1457, "**1457_DPT_2022_EISA_SCSI_Controller**" in the "Known Problems" section about setting the cache to "Enabled (Write-Back)."

For more information on the DPT 2022 SCSI Controller, see NeXTanswer #1457, "1457_DPT_2022_EISA_SCSI_Controller."

Known Problems:

Releases 3.2 and 3.1

• The mouse that ships with the ALR may cause the cursor to exhibit jerky behavior. Swapping the mouse for another brand of PS/2 mouse solves the problem.

Release 3.1

- When you install NEXTSTEP Release 3.1, the error "Floppy Controller Reset: Command Timeout" is reported. The computer continues to retry and to recalibrate the floppy disk drive for about ten minutes before giving up and skipping the floppy disk drive. Installation proceeds normally after this. To avoid the delay, eject the floppy disk manually after the computer displays the message "NeXT Mach 3.1" but before it registers the floppy disk drive controller fc0. This problem has been fixed in Release 3.2.
 - When you use NEXTSTEP Release 3.1 on some Evolution IV computers, the clock jumps ahead about 22 minutes at random times. This problem hasn't been seen in Release 3.2.