

NOTE: This Technical Note has been [retired](#). Please see the [Technical Notes](#) page for current documentation.

Technical Note HW02

ADBReInit on the SE with System 4.1: Don't Call It

CONTENTS

[References](#)

[Downloadables](#)

Because of a bug (which causes auto-repeat) in the ROM version of the Macintosh SE keyboard driver, a patch was placed in System 4.1. If `ADBReInit` is called, the ROM version of the keyboard driver will be reloaded, and the RAM version of the driver with the patches will not be used. Therefore, it is recommended that `ADBReInit` not be called on the Macintosh SE until the problem is fixed. (There is no need to call `ADBReInit`.) This problem will not occur with the Macintosh II ROM version of the keyboard driver.

[Jul 01 1987]

References

The Apple Desktop Bus

[Back to top](#)

Downloadables



Acrobat version of this Note (K)

[Download](#)

[Back to top](#)

Technical Notes by [Date](#) | [Number](#) | [Technology](#) | [Title](#)
[Developer Documentation](#) | [Technical Q&As](#) | [Development Kits](#) | [Sample Code](#)