


# New Technical Notes

Macintosh



---

Developer Support

## Don't Call ADBReInit on the SE with System 4.1

Hardware

M.HW.ADBReInit

Revised by:

March 1988

Written by: Mark Baumwell

July 1987

---

Because of a bug (which causes auto-repeat) in the ROM version of the Macintosh SE keyboard driver, a patch was placed in System 4.1. If `ADBReInit` is called, the ROM version of the keyboard driver will be reloaded, and the RAM version of the driver with the patches will not be used. Therefore, it is recommended that `ADBReInit` not be called on the Macintosh SE until the problem is fixed. (There is no need to call `ADBReInit`.) This problem will not occur with the Macintosh II ROM version of the keyboard driver.

### Further Reference:

---

- The Apple Desktop Bus