

Apple II Technical Notes



Developer Technical Support

ProDOS 8

#10: Installing Clock Driver Routines

Revised by:	Matt	Deatherage
November 1988		
Revised by:	Pete	McDonald
November 1985		

This Technical Note formerly described how to install a clock driver routine other than the default.

Section 6.1.1 of the *ProDOS 8 Technical Reference Manual* documents how to install a clock driver other than the default ThunderClock™ driver or the Apple IIGS clock driver into ProDOS 8, which this Note formerly covered.

Further Reference

- *ProDOS 8 Technical Reference Manual*
- ProDOS 8 Technical Note #1, The GETLN Buffer and a ProDOS Clock Card