

# Apple II Technical Notes



---

Developer Technical Support

## Apple IIGS

### #13: ROM 1.0 Modem Firmware Bug

Revised by: Matt Deatherage  
November 1988

Written by: Mike Askins April  
1986

This Technical Note formerly discussed a bug involving buffering and serial port setting commands in the modem firmware in ROM 1.0.

---

Apple IIGS ROM 2.0 fixes a bug involving buffering and serial port setting commands in the modem firmware. You should not have to write a special case to handle this bug since it is reasonable to expect users to have the updated ROM which is offered as a free upgrade from Apple.