

Sheet1

SEX,C,1	FNAME,C,20	LNAME,C,20	PROSPECT	DATE_SY	TIME_SY	ADDRESS1,C
	Kenworth K100	GR45339264T50	UTR399	06/25/80	00:03:36	
	Kenworth K100	GR45339264T50	UTR399	02/10/81	00:08:10	
	Kenworth K100	GR45339264T50	UTR399	03/25/83	00:10:54	
	Mack Truck, #R-685	55823WSE90321	STW366	12/30/82	00:16:31	
	Mack Truck, #R-685	55823WSE90321	STW366	05/26/83	00:20:27	
	Mack Truck, #R-685	55823WSE90321	STW366	08/23/84	00:24:05	
	Peterbilt, #362	3356UST217431	WRX332	01/02/83	00:30:07	
	Peterbilt, #362	3356UST217431	WRX332	05/28/84	00:33:55	
	Peterbilt, #362	3356UST217431	WRX332	06/28/84	00:38:47	
	Mack Truck, #R-685	55823WSE90321	STW366	01/01/86	17:21:13	
	Kenworth K100	GR45339264T50	UTR399	01/01/86	17:24:17	
	Peterbilt, #362	3356UST217431	WRX332	01/01/86	17:25:55	
	Mack Truck, #R-685	55823WSE90321	STW366	01/01/86	17:27:38	
	Kenworth K100	GR45339264T50	UTR399	01/01/86	17:28:57	
	Peterbilt, #362	3356UST217431	WRX332	01/01/86	17:30:36	
	Mack Truck, #R-685	55823WSE90321	STW366	01/01/86	17:32:13	
	Kenworth K100	GR45339264T50	UTR399	01/01/86	17:33:37	
	Peterbilt, #362	3356UST217431	WRX332	01/01/86	17:36:45	
	001NEW1	001NEW1	001NEW1	05/15/89	00000000	
	000NEW1	000NEW1	000NEW1	05/15/89	00000000	
	000	000	000	05/15/89	00:00:00	

ADDRESS2,C,CITY,C,1	STATE,C,2	ZIFPHONE_1,C,1
		0
		0
		0
		0
		0
		0
		0
		0
		0
		0
		0
		0
		0
		0
		0
		0
		0
		0
		0
		0

Sheet1

COMMENT1,C,201

Brought truck back into shop for loose muffler.

Air conditioner pump leaking freon.

Carburetor adjusting value stripped, engine emitting high level of pollutants. Replace carburetor.

Service manual for this model #R-685, conventional Mack Truck missing. Ordered new one.

Bracket for driver seat missing. Seat fails to position correctly. Reclines without moving forward. Replaced bracket.

Sluggish truck performance. Compression readings in cylinders show worn rings. Replace rings and check compression in 6

Howling coming from rear axle. Replace hypoid gears.

Continued problems with howling coming from rear axle. Drained fluid and again identified small metal particles, larger than s

Brought Cabover truck back for 30 day check out after rear axle problems in May. Drained hypoid fluid in rear axle and discov

Order fan belts for this truck. Check with parts distributor tomorrow.

Schedule driver to drop off truck in 3 days for service.

Perform state inspection on vehicle in 1 week.

Schedule this truck for state inspection in 2 days.

Perform the state vehicle inspection in 5 days.

Contact parts distributor in one week for new tires for this truck.

Check toe-in, toe-out in 9 days.

Schedule yearly preventive maintenance in 11 days.

Schedule yearly preventive maintenace.

Ignore this record, used to guide appointments index.

Ignore this record, used to guide appointments index.

Ignore this record, used on top of each Category

Sheet1

COMMENT2,(DEL_DATE)EXPENSEINCLPROSPMEMCMACT1,N,4,0 MACT2,C,4

01/01/01	0.00	1	0
01/01/01	0.00	1	0
01/01/01	0.00	1	0
01/01/01	35.00	1	0
01/01/01	55.00	1	0
02/23/85	350.00	1	0
01/01/01	450.00	1	0
06/28/84	50.00	1	0
01/01/01	850.00	1	0
01/02/86	0.00	1	0
01/04/86	0.00	1	0
01/09/86	0.00	1	0
01/03/86	0.00	1	0
01/06/86	0.00	1	0
01/08/86	0.00	1	0
01/10/86	0.00	1	0
01/11/86	0.00	1	0
01/03/86	0.00	1	0
01/02/01		0	
05/15/89		0	
01/01/01		0	