

LANSource™ Technical Information

LANSource Technologies Inc. 221 Dufferin St., Suite 310A Toronto, Ontario M6K 3J2 CANADA

Topic Number: WXP5011

Subject: Mixing WINport 4.05b Modem Servers with WINport 5.0a 32-bit Modem Servers

Release Date: 10/11/95 Total number of pages: 1 Revision: 1.0

1.0 Situation

When you operate a WINport 4.05b 16-bit Modem Server with WINport 5.0a Modem Server in Windows NT Server, an error occurs.

1.1 Description of problem

In the event log, the following error will be displayed:

NetBIOS bind = 0x2726

1.2 Solution to problem

There is no solution, only a 'work-around' at this time. This is to:

Set the NT modem number to a number that is one higher than the highest on the old server (but still staying under the total allowed).

The error message will then stop showing in the event log.

All technical information is Copyright © 1995 LANSource Technologies Inc. - All Rights Reserved World Wide - FAXport, WINport, RASport and DOSport are Registered Trademarks (™) of LANSource Technologies Inc. -Other product names are Trademarks of the respective companies

To contact LANSource: Telephone (416) 535-3555 - FAX (416) 535-6225 - BBS (416) 535-5878 - CompuServe go LANSource - Internet through <http://www.lansource.com>