



ES8509-XT

Firmware History (1800400)

Changes in v1.4

- Upgraded to Bootloader v1.3.1.5
- Upgrade web interface for IPv6 Gold Logo certification
- Modify web interface to match the new RocketLinx web page look
- Change string "Factory default" to "Load default" in web page
- Keep DHCP Client and Default Gateway setting when load default configuration
- Fix IGMP IP subnet mask check
- Fix NetVision discovery bug
- Update web interface with a signed JAR file so that Java 7/Update 51 permits the web interface to open using the Java default security settings.
- Supports PortVision DX

Changes v1.3a

- Fixed web interface Reboot bug
- Updated Logout popup message

Changes from v1.1 to v1.3

- IPv6 release
- Adds port-based DHCP server config
- Adds Option82 DHCP server config and relay agent
- STP State (enable/disable) added to the STP Port Config so you can disable the STP state when connecting a device to avoid STP waiting periods.
- Loop Protection feature added.
- GMRP Configuration feature added.
- Alarms support multi-alarm feature.
- Updated Warning - Event Selection.
- VLAN Config help fixed: 256 max VLAN.
- CLI additions include:

- *Exec mode* → list: show arp and traceroute ipv6 WORD
- *Global Config mode* → ipv6, loop-protect, modbus, and service
- *VLAN Interface Config mode* → ipv6
- Modified the SSL Certificate Name.
- Added show service command in CLI