The Quit command allows the user to exit the program. If the current parameter set has not yet been saved,the user will be prompted to do so.