LANSource ™ Technical Information

LANSource Technologies Inc. 221 Dufferin St., Suite 310A Toronto, Ontario M6K 3J2 CANADA

Topic Number: Quick Guide 1

Subject: *To install the 32 bit FAXport server on NT (or WIN 95 if 5.0b):*

Release Date: 12/04/95 Total number of pages: 1 Revision: 1. 1

1. Before you begin the installation, ensure you are logged into the NT server as the Administrator.

2. Run SETUP.EXE from root directory of CD ROM. This will copy files to a directory on the hard drive. (Make certain that the installation is to the C: Drive only.)

3. During the install you will be asked for a UNC path for the Network shared phonebook. Enter "\\ servername\phone" and change the servername for the NT's machine name.

4. You will be asked to brand the software. Enter a WINport or FAXport license number.

5. After branding you will have a FAXport group with a BRAND32, Install, and Uninstall icons. Run the Install icon. It will report Install Service Successful.

6. Next go to the File manager and create a directory under the FAXport server directory called phone. Then share this directory as "Phone".

7. Go to control panel and select the Services icon.

8. Highlight the FAXport/WINport server and select the Startup button.

9. Ensure that the service is set to log in as Administrator under "This Account."

10. Start the service. Ensure the service FAXport/WINport 5.0 has started. Ignore the initial errors.

The FAXport Administrator is not required at this point in the installation. The FAXport Administrator is a separate program used to setup and configure the FAXport Server.

Be certain to have ODBC installed at the server.

NOTE: The FAXport 16 Bit Administrator cannot be run from the FAXport Server workstation station, only from a separate workstation station where the first FAXport Client is installed!

See Quicknote Number 3: Running FAXport Administrator program, for more information on running and using that program