Axis Conversion Inspector

Temperature Axis Conversion
The X or Y axis can be converted from degrees Celsius or
Fahrenheit to degrees Kelvin and vice versa.

PES Axis Conversion
This function converts the energy (X) axis of photo electron
spectra depending on the excitation energy, from binding
energy to kinetic energy and vice versa.

XRD Axis Conversion
This function converts the X axis of X-ray diffraction spectra
depending on the X-ray wavelength, from 2Theta to d and
vice versa.