# Apple II
Technical Notes

®

Developer Technical Support

Apple IIGS
#59: Do Not Create Zero-Length Text Scraps

Revised by: Dave   Lyons
          January 1991
Written by: Dave Lyons   July
    1989

This Technical Note described a problem with zero-length text scraps.
Changed since July 1989: This Note is obsolete beginning with System Software 5.0.3. There is no longer a problem with creating a text scrap of length zero.

In System Software 5.0.3 and later, `LEFromScrap` no longer trashes memory if you create a text scrap (scrap type 0) with length zero.

Further Reference
- *Apple IIGS Toolbox Reference,* Volume 2