Macintosh Technical Notes

#83: System Heap Size Warning

See also: The Memory Manager

Written by: Jim Friedlander   June 21, 1986
Updated: March 1, 1988

Earlier versions of this note pointed out that, due to varying system heap sizes, the application heap does not always start at `$CB00`. The start of the application heap has not been fixed for some time now; programs that depend on it never work on the Macintosh SE or the Macintosh II.