MS-5163 W563MS41 BIOS Release
----

1. This is an AWARD BIOS ver 4.1 release.

2. This BIOS fixes the following problems of the previous version:
    - Fixed the problem of Cyrix 83.3Mhz CPU in which it will hang in
       Windows®95 when you click drive A.
    - Fixed Boot sequence problem.
    - Added Typematic Keyboard function.
    - Added support for SDMS 3.0.
    - Added boot up floppy seek function.
    -
** Please refer to FLASH.DOC for programming notes.