


\*\*\*\*\*  
 \* THE HOW TO SERIES \*  
 \* PART III \*  
 \* TRON BOX \*  
 \* BY: CAP'N CRUNCH \*  
 \* CALL /-APRIL WINE [913] 236-4493 \*  
 \* MONOLITH PRODUCTIONS \*  
 \*\*\*\*\*



(C)=CAPACITOR  
 F =FUZE  
 R =RESISTOR  
 I,- ARE WIRE  
 PARTS LIST:

- (3) ELECTROLYTIC CAPACITORS  
 RATED AT 50V(LOWEST) .47UF
- (1) 20-30OHM 1/2 WATT RESISTOR
- (1) 120VOLT FUSE (AMP RATING BEST  
 TO USE AT LEAST HALF OF TOTAL  
 HOUSE CURRENT OR EVEN LESS IT  
 KEEPS YOU FROM BLOWING YOUR  
 BREAKER JUST IN CASE...)
- (1) POWER CORD (CUT UP AN EXTENSTION  
 CORD. NEED PLUG PART AND WIRE)
- (1) ELECTRICALLY INSULATED BOX

REST OF SIF YOUR DONT FILL COMFORTABLE  
 ABOUT  
 ELECTRICITY THEN DONT PLAY WITH THIS  
 THERE IS VOLTAGE PRESENT THAT WILL  
 \*\*\*KILL \*\*\* YOU.....

