<u>SCSI: HDI-30</u> <u>Serial Ports: 2</u> <u>Sound Output: stereo 8 bit.</u> <u>ADB: 1</u> <u>Ethernet: none</u> <u>Machine Gestalt ID: 34</u> PRAM Battery: service center replacement only

<u>Minutiae:</u>

<u>10" Supertwist LCD - 4 bit (16 Grays) Display.</u>

<u>Pseudo-static modules designed for the older PowerBook 100, 140, 145 and 170 may work in the 160, but will sacrifice performance because they add wait states that are not necessary with this machine. (See Newer Technology freeware "Nightmare on PowerBook Street" to detect the problem described above. This freeware program is available on our web pages).</u>

Has 1MB ROM and a 1.44MB SuperDrive.