

Current Limitations and Known bugs:

- No Hi-Speed Isochronous Support
- No Split Transaction Support
- No Remote Wakeup Support
- No Over Current Detection Support
- May have problem when plugging in and out during Stand-by, transition to Stand-by or transition to Resume

Fixes in this release:

- Fix play back for Video CDs with Win2K
- Transmit correct zero length for out packet during bulk transaction
- Fix occasional hang of transmitting packets over 16KB.
- Correct Error handling
- Fix occasional problem writing CDs with B'z Recorder Gold under 98Gold
- Fix transaction stop when writing CD-RW and using CATC
- Improve recognition of Full speed devices
- Improve bus speed for PC Cards