

## TABLE OF CONTENTS

|   |      |
|---|------|
| <b>PERSONAL COMPUTERS</b>               | 2, 3 |
| FRENCH UPGRADES                         | 3    |
| MEMORY UPGRADES                         | 4    |
| MODEMS                                  | 5    |
| CARRYING CASES                          | 5    |
| BATTERY ACCESSORIES                     | 6    |
| EXPANSION                               | 6    |
| AC/AUTO ADAPTERS                        | 7    |
| OTHER ACCESSORIES                       | 7    |
| <br><b>ADVANCED TECHNOLOGY PRODUCTS</b> |      |
| CD-ROM DRIVES & ACCESSORIES             | 8    |
| SMART DRIVES                            | 8    |
| <br><b>PRINTERS</b>                     | 9    |
| PRINTER SUPPLIES                        | 9    |
| PRINTER ACCESSORIES                     | 9    |
| LASER PRINTER SUPPLIES                  | 9    |

- NOTES:**
- o **ALL PRODUCTS SHOWN IN ITALICS ARE SPECIALLY PRICED, ARE SUBJECT TO AVAILABILITY, AND MAY NOT BE RETURNED FOR STOCK ROTATION, CREDITS, ETC.**
  - o **ALL PRICING AND SPECIFICATIONS SUBJECT TO CHANGE WITHOUT NOTICE.**
  - o **IF YOU REQUIRE A PRODUCT THAT HAS BEEN DISCONTINUED (i.e. NOT LISTED IN THIS HANDBOOK), PLEASE CONTACT THE TOSHIBA ORDER DESK TO CHECK AVAILABILITY. SUCH REQUESTS WOULD BE CONSIDERED A "SPECIAL ORDER PRODUCT" AND CANNOT BE CANCELLED, OR AVAILABLE FOR EXCHANGE OR RETURN.**

**PERSONAL COMPUTERS**

| <b>PRODUCT #</b>   | <b>DESCRIPTION</b>  | <b>CDN LIST PRICE</b> |
|--------------------|---|-----------------------|
| <b>T1900/120</b>   | Notebook PC w/80486SX, 20 MHz Processor, 4MB Memory, 120MB Hard Disk Drive, PCMCIA Slot and 9.5" Sidelit Supertwist LCD Display.  | Err:511               |
| <b>T1900C/200</b>  | Notebook PC w/80486SX, 20 MHz Processor, 4MB Memory, 200MB Hard Disk Drive, PCMCIA Slot and 9.5" Enhanced STN Colour LCD Display.   | Err:511               |
| <b>T1950/200</b>   | Notebook PC w/80486DX2, 40 MHz Processor, 4MB Memory, 200MB Hard Disk Drive, PCMCIA Slot and 9.5" Sidelit Supertwist LCD Display.   | Err:511               |
| <b>T1950CS/200</b> | Notebook PC w/80486DX2, 40 MHz Processor, 4MB Memory, 200MB Hard Disk Drive, PCMCIA Slot and 9.5" Enhanced STN Colour LCD Display.  | Err:511               |
| <b>T1950CT/320</b> | Notebook PC w/80486DX2, 40 MHz Processor, 4MB Memory, 320MB Hard Disk Drive, PCMCIA Slot and 8.4" Colour Active Matrix TFT LCD Display.   | Err:511               |
| <b>T3400/120</b>   | Sub-notebook PC w/80486SX, 33 MHz Processor, 4MB Memory, 120MB Hard Disk Drive, PCMCIA Slot and 8.4" Sidelit Supertwist LCD Display.  | Err:511               |
| <b>T3400CT/120</b> | Sub-notebook PC w/80486SX, 33 MHz Processor, 4MB Memory, 120MB Hard Disk Drive, PCMCIA Slot and 7.8" Colour Active Matrix TFT LCD Display.  | Err:511               |
| <i>T4500/200</i>   | <i>Notebook PC w/i486SX (3.3V), 20 MHz Processor, 4MB Memory, 200MB Hard Disk Drive, PCMCIA Slot and 9.5" Sidelit Supertwist LCD Display.</i>   | <i>Err:511</i>        |
| <i>T4500C/200</i>  | <i>Notebook PC w/i486SX (3.3V), 20 MHz Processor, 4MB Memory, 200MB Hard Disk Drive, PCMCIA Slot and 8.4" Colour Active Matrix TFT LCD Display.</i>                                   | <i>Err:511</i>        |
| <i>T4600/200</i>   | <i>Notebook PC w/i486SL, 33 MHz Processor, 4MB Memory, 200MB Hard Disk Drive, Two PCMCIA Slots and 9.5" Sidelit Supertwist LCD Display.</i>   | <i>Err:511</i>        |
| <b>T4600C/200</b>  | Notebook PC w/i486SL, 33 MHz Processor, 4MB Memory, 200MB Hard Disk Drive, Two PCMCIA Slots and 9.5" Colour Active Matrix TFT LCD Display.  | Err:511               |
| <b>T4600C/320</b>  | Notebook PC w/i486SL, 33 MHz Processor, 4MB Memory, 320MB Hard Disk Drive, Two PCMCIA Slots and 9.5" Colour Active Matrix TFT LCD Display.  | Err:511               |
| <b>T4700CT/320</b> | Notebook PC w/i486DX2, 50 MHz Processor, 8MB Memory, 320MB Hard Disk Drive, Two PCMCIA Slots and 9.5" Colour Active Matrix TFT LCD Display.   | Err:511               |
| <b>T6600C/510</b>  | Mobile Multimedia PC w/i486DX2, 66 MHz Processor, 8MB Memory, 510MB Hard Disk Drive and 10.4" Colour Active Matrix TFT-LCD Display, expansion slots/bay and MS Sound System built-in. | Err:511               |

**PERSONAL COMPUTERS - Continued**

| <b>PRODUCT #</b>      | <b>DESCRIPTION</b>                         | <b>CDN LIST PRICE</b> |
|-----------------------|--|-----------------------|
| <b>FC-T1900/120</b>   | French Canadian Model of T1900/120         | Err:511               |
| <b>FC-T1900C/200</b>  | French Canadian Model of T1900C/200        | Err:511               |
| <b>FC-T1950/200</b>   | French Canadian Model of T1950/200         | Err:511               |
| <b>FC-T1950CS/200</b> | French Canadian Model of T1950CS/200       | Err:511               |
| <b>FC-T1950CT/320</b> | French Canadian Model of T1950CT/320       | Err:511               |
| <b>FC-T3400/120</b>   | French Canadian Model of T3400/120         | Err:511               |
| <b>FC-T3400CT/120</b> | French Canadian Model of T3400CT/120       | Err:511               |
| <i>FC-T4500/200</i>   | <i>French Canadian Model of T4500/200</i>  | <i>Err:511</i>        |
| <i>FC-T4500C/200</i>  | <i>French Canadian Model of T4500C/200</i> | <i>Err:511</i>        |
| <i>FC-T4600/200</i>   | <i>French Canadian Model of T4600/200</i>  | <i>Err:511</i>        |
| <b>FC-T4600C/200</b>  | French Canadian Model of T4600C/200        | Err:511               |
| <b>FC-T4600C/320</b>  | French Canadian Model of T4600C/340        | Err:511               |
| <b>FC-T4700CT/320</b> | French Canadian Model of T4700CT/340       | Err:511               |
| <b>FC-T6400C/200</b>  | French Canadian Model of T6600C/510        | Err:511               |

**FRENCH UPGRADES**

| <b>PRODUCT #</b>    | <b>DESCRIPTION</b>   | <b>CDN LIST PRICE</b> |
|---------------------|--|-----------------------|
| <i>FC-T1800-U</i>   | <i>T1800 Series French Canadian Kit (T1800/T1850/T1850C)</i> | <i>Err:511</i>        |
| <b>FC-T1900-U</b>   | T1900 Series French Canadian Kit (T1900/T1900C)              | Err:511               |
| <b>FC-T1950-U</b>   | T1950 Series French Canadian Kit (T1950/T1950CS/T1950CT)     | Err:511               |
| <b>FC-T3400-U</b>   | T3400 Series French Canadian Kit (T3400/T3400CT)             | Err:511               |
| <i>FC-T4400SX-U</i> | <i>T4400 Series French Canadian Kit (T4400SX/SXP/SXC/C)</i>  | <i>Err:511</i>        |
| <b>FC-T4500-U</b>   | T4500 Series French Canadian Kit (T4500/T4500C)              | Err:511               |
| <b>FC-T4600-U</b>   | T4600 Series French Canadian Kit (T4600/T4600C)              | Err:511               |
| <b>FC-T4700-U</b>   | T4700CT French Canadian Kit                                  | Err:511               |
| <i>FC-T6400-U</i>   | <i>T6400 Series French Canadian Kit (T6400/C/SX/DX/DXC)</i>  | <i>Err:511</i>        |
| <b>FC-T6600-U</b>   | T6600C French Canadian Kit                                   | Err:511               |

**MEMORY UPGRADES**

| <b>PRODUCT #</b> | <b>DESCRIPTION</b>  | <b>CDN LIST PRICE</b> |
|------------------|---|-----------------------|
| PA2000U          | T1000LE/T1800/T1850/C/T2000/SX/SXe/T2200SX 2MB Memory       | Err:511               |
| PA2001U          | T1000LE/T1800/T1850/C/T2000/SX/SXe/T2200SX 4MB Memory       | Err:511               |
| PA2002U          | T1000LE/T1800/T1850/C/T2000/SX/SXe/T2200SX 8MB Memory       | Err:511               |
| PA2003U          | T4400SX/T4400C/T6400SX/T6400DX/T6400DXC/T6600C 2MB Memory   | Err:511               |
| <b>PA2004U</b>   | T4400SX/T4400C/T6400SX/T6400DX/T6400DXC/T6600C 4MB Memory   | Err:511               |
| <b>PA2005U</b>   | T4400SX/T4400C/T6400SX/T6400DX/T6400DXC/T6600C 8MB Memory   | Err:511               |
| PA2006U          | T3300SL 2MB Memory  | Err:511               |
| PA2007U          | T3300SL 4MB Memory  | Err:511               |
| PA2008U          | T3300SL 6MB Memory  | Err:511               |
| PA2009U          | T3300SL 16MB Memory   | Err:511               |
| <b>PA2010U</b>   | T4400SX/T4400C/T6400SX/T6400DX/T6400DXC/T6600C 16MB Memory  | Err:511               |
| <b>PA2012U</b>   | T1900/C, T1950/CS/CT, T4500/C, T4600/C, T4700CT 4MB Memory  | Err:511               |
| <b>PA2013U</b>   | T1900/C, T1950/CS/CT, T4500/C, T4600/C, T4700CT 8MB Memory  | Err:511               |
| <b>PA2014U</b>   | T1900/C, T1950/CS/CT, T4500/C, T4600/C, T4700CT 16MB Memory | Err:511               |
| <b>PA2019U</b>   | T3400/T3400CT 4MB Memory                                    | Err:511               |
| <b>PA2020U</b>   | T3400/T3400CT 8MB Memory                                    | Err:511               |
| <b>PA2021U</b>   | T3400/T3400CT 16MB Memory                                   | Err:511               |
| PA7134           | T1000 768 KB Memory   | Err:511               |
| PA8311           | T1000SE/T1000XE/T1000LE 1MB Memory                          | Err:511               |
| PA8312           | T1000SE/T1000XE/T1000LE 2MB Memory                          | Err:511               |
| PA8314           | T1000LE/T2000/T2000SX 4MB Memory                            | Err:511               |
| PA7139           | T1200 1MB Memory  | Err:511               |
| PA8306           | T1200XE 2MB Memory  | Err:511               |
| PA8316           | T2000/T2000SX 1MB Memory                                    | Err:511               |
| PA7137           | T3200 3MB Memory  | Err:511               |
| PA8307           | T3200SX 2MB Memory  | Err:511               |
| PA8301           | T5100 2MB Memory  | Err:511               |

**MODEMS**

| <b>PRODUCT #</b> | <b>DESCRIPTION</b>   | <b>CDN LIST PRICE</b> |
|------------------|--|-----------------------|
| T24M             | <i>Error Correcting 1200/2400 Baud Card Modem (for T2200SX)</i>  | <i>Err:511</i>        |
| BC2400M          | <i>Error Correcting 300/1200/2400 Baud Internal Modem<br/>(for T1000SE/XE/LE/T1200/XE/T1600/T1800/T1850/C/<br/>T2000/SX/SXe/T3100SX/T3200SX/SXC/T4400/T6400)</i> | <i>Err:511</i>        |

**CARRYING CASES**

| <b>PRODUCT #</b> | <b>DESCRIPTION</b>  | <b>CDN LIST PRICE</b> |
|------------------|---|-----------------------|
| BC7520           | <i>Notebook Slipcase, Nylon with handle and shoulder strap.<br/>(for T1800 Series, T1900 Series, T1950 Series, T2200SX, T3300SL,<br/>T3400 Series, T4400 Series, T4500 Series, T4600 Series and T4700CT)</i>            | <i>Err:511</i>        |
| BC7521           | Notebook Deluxe Nylon with room for portable printer with shoulder strap (for T1800 Series, T1900 Series, T1950 Series, T2200SX, T3300SL, T3400 Series, T4400 Series T4500 Series, T4600 Series and T4700CT)            | Err:511               |
| BC7522           | Leather Notebook Deluxe Case with handle & shoulder strap.<br>(for T1800 Series, T1900 Series, T1950 Series, T2200SX, T3300SL, T3400 Series, T4400 Series, T4500 Series, T4600 Series and T4700CT)                      | Err:511               |
| BC7523           | Leather Notebook Carrying Case with handle & shoulder strap.<br>with shoulder strap (for T1800 Series, T1900 Series, T1950 Series, T2200SX, T3300SL, T3400 Series, T4400 Series T4500 Series, T4600 Series and T4700CT) | Err:511               |
| BC7530           | Hardsided ABS Notebook Deluxe Case with handle & shoulder strap.<br>(for T1800 Series, T1900 Series, T1950 Series, T2200SX, T3300SL, T3400 Series, T4400 Series, T4500 Series, T4600 Series and T4700CT)                | Err:511               |
| BC7564           | <i>T6400 Nylon Case with handle &amp; shoulder strap,<br/>outside pocket for files and cables. (for T6400 series)</i>   | <i>Err:511</i>        |
| BC7566           | T6600C Carrying Case made from 'Koskin' with handle & shoulder strap, outside pocket for files and cables.  | Err:511               |
| PA8723           | <i>P201/P301 Nylon Carrying Case</i>  | <i>Err:511</i>        |
| BC7501           | <i>Leather Carrying Case for all portables and portable printer<br/>with outside pocket and shoulder strap</i>  | <i>Err:511</i>        |
| BC7506           | <i>Nylon Carrying Case for XM-3201PORT/XM-3301 Port</i>   | <i>Err:511</i>        |

**BATTERY ACCESSORIES**

| <b>PRODUCT #</b> | <b>DESCRIPTION</b>   | <b>CDN LIST PRICE</b> |
|------------------|--|-----------------------|
| <b>PA2404U</b>   | T2200SX/T3300SL Additional Nickel Metal Hydride Battery Pack       | Err:511               |
| <b>PA2407U</b>   | T4400SX/T4400C Additional Nickel Cadmium Battery Pack              | Err:511               |
| <b>PA2410U</b>   | T1800/T1850 Additional Battery Pack                                | Err:511               |
| <b>PA2412U</b>   | T4500/T4600 Additional Nickel Cadmium Battery Pack                 | Err:511               |
| <b>PA2413U</b>   | T4500C/T4600C/T4700CT Additional Nickel Metal Hydride Battery Pack | Err:511               |
| <b>PA2420U</b>   | T1900/C, T1950/CS/CT Additional Nickel Metal Hydride Battery Pack  | Err:511               |
| <b>PA2422U</b>   | T1900/C, T1950/CS/CT Battery Charger (takes two batteries)         | Err:511               |
| <b>PA2481U</b>   | T3400/T3400CT Additional Lithium Ion Battery Pack                  | Err:511               |
| <b>PA2482U</b>   | T3400/T3400CT Battery Charger (takes two batteries)                | Err:511               |
| <i>PA8712</i>    | <i>T1000SE/XE/LE/T1200XE Additional Battery Pack</i>               | <i>Err:511</i>        |
| <i>PA8719</i>    | <i>T1000LE Optional 2nd Battery Pack (Modem Slot)</i>              | <i>Err:511</i>        |
| <i>PA7490</i>    | <i>T1200 Battery Charger (3 slots, batteries not included)</i>     | <i>Err:511</i>        |
| <i>PA7491</i>    | <i>T1200 Additional Battery Pack</i>                               | <i>Err:511</i>        |
| <i>PA8715</i>    | <i>T1600 Additional Battery Pack</i>                               | <i>Err:511</i>        |
| <i>PA2403</i>    | <i>T2000 Additional Battery Pack</i>                               | <i>Err:511</i>        |
| <i>PA8725</i>    | <i>T2000SX/SXe Additional Nickel Hydride Battery Pack</i>          | <i>Err:511</i>        |
| <i>PA8707</i>    | <i>T3100SX Battery Charger (3 slots, batteries not included)</i>   | <i>Err:511</i>        |
| <i>PA8708</i>    | <i>T3100SX Additional Battery Pack</i>                             | <i>Err:511</i>        |

**EXPANSION**

| <b>PRODUCT #</b> | <b>DESCRIPTION</b>   | <b>CDN LIST PRICE</b> |
|------------------|--|-----------------------|
| <b>PA2701U</b>   | Desk Station IV (T2200SX/T3300SL/T4400 Series/T4500 Series/<br>T4600 Series/T4700CT/T6400 Series)        | Err:511               |
| <b>PA2703U</b>   | Port Replicator (T3400/T3400CT)  | Err:511               |
| <b>PA2113</b>    | 150-pin SCSI-2 Adapter (T2200SX/T3300SL/T4400 Series/T4500 Series/<br>T4600 Series/T4700CT/T6400 Series) | Err:511               |
| <b>PA510L</b>    | MediaShare Mambo DVI/Ethernet Board for T6400 Series/T6600C  | Err:511               |
| <i>PA8380</i>    | <i>3.5" External Floppy Disk Drive (T1000XE)</i>   | <i>Err:511</i>        |
| <i>PA8601</i>    | <i>Desk Station III (T3100SX)</i>  | <i>Err:511</i>        |

**AC/AUTO ADAPTERS**

| <b>PRODUCT #</b> | <b>DESCRIPTION</b>   | <b>CDN LIST PRICE</b> |
|------------------|--|-----------------------|
| <b>PA2400U</b>   | T2000/T2200SX/T3300SL Extra Universal AC Adapter             | Err:511               |
| <b>PA2408U</b>   | T4400SX/T4400C Extra Universal AC Adapter                    | Err:511               |
| <b>PA2409U</b>   | T1800/T1850 Extra Universal AC Adapter                       | Err:511               |
| <b>PA2411U</b>   | T1850C, T4500/C, T4600/C, T4700CT Extra Universal AC Adapter | Err:511               |
| <b>PA2417U</b>   | T1900/T1950 Extra Universal AC Adapter                       | Err:511               |
| <b>PA2426U</b>   | T3400/T3400CT Extra Universal AC Adapter                     | Err:511               |
| <b>PA2478U</b>   | T1900C/T1950CS/T1950CT Extra Universal AC Adapter            | Err:511               |
| <i>PA7483</i>    | <i>T1000 Automobile Adapter</i>                              | <i>Err:511</i>        |
| <i>PA8701</i>    | <i>T1000 Universal AC Adapter</i>                            | <i>Err:511</i>        |
| <i>PA8706</i>    | <i>T1000XE/LE/T1200/XE Extra Universal AC Adapter</i>        | <i>Err:511</i>        |
| <i>PA7485</i>    | <i>T1200 Extra Universal AC Adapter</i>                      | <i>Err:511</i>        |
| <i>PA7487</i>    | <i>T1600 Extra Universal AC Adapter</i>                      | <i>Err:511</i>        |
| <i>PA8727</i>    | <i>T2000SX/T2000SXe Extra Universal Adapter</i>              | <i>Err:511</i>        |
| <i>PA8709</i>    | <i>T3100SX Extra Universal AC Adapter</i>                    | <i>Err:511</i>        |

**OTHER ACCESSORIES**

| <b>PRODUCT #</b> | <b>DESCRIPTION</b>  | <b>CDN LIST PRICE</b> |
|------------------|---|-----------------------|
| <b>PA2803U</b>   | 128KB internal turbo cache for T6600C   | Err:511               |
| <i>PA7354</i>    | <i>Numeric Keypad (for T1000/T1200/T1200XE/T1600/T1800/T1850/C/<br/>T2000/SX/SXe/T2200SX/T3100SX/T3300SL/T4400SX/C)</i> | <i>Err:511</i>        |
| <i>PA8718</i>    | <i>101-key Keyboard Adapter with AC Adapter (for T1800/T1850/C/<br/>T2000/SX/SXe/T2200SX/T3100SX/T3300SL/T4400SX/C)</i> | <i>Err:511</i>        |
| <i>PA8380</i>    | <i>3.5" External Floppy Disk Drive (T1000XE)</i>  | <i>Err:511</i>        |
| <i>PA2800U</i>   | <i>T6400SX/T6400DX/T6400DXC Processor Upgrade to i486DX2-50</i>   | <i>Err:511</i>        |

**CD-ROM DRIVES**

| <b>PRODUCT #</b> | <b>DESCRIPTION</b>   | <b>CDN LIST PRICE</b> |
|------------------|--|-----------------------|
| <b>XM-3401B</b>  | Internal CD-ROM drive with 200ms access time, 330KB/s throughput, multisession and multispeed capabilities | Err:511               |
| <b>TXM-3401E</b> | External CD-ROM drive with 200ms access time, 330KB/s throughput, multisession and multispeed capabilities | Err:511               |
| <b>NOTE:</b>     | Select appropriate Interface Kit from CD-ROM Accessories   |                       |

**CD-ROM ACCESSORIES**

| <b>PRODUCT #</b>      | <b>DESCRIPTION</b>   | <b>CDN LIST PRICE</b> |
|-----------------------|--|-----------------------|
| <b>3401-PCF KIT</b>   | PC XT/AT (ISA-bus) Kit for TXM-3401E External CD-ROM Drive   | Err:511               |
| <b>3401-PCF-B KIT</b> | PC XT/AT (ISA-bus) Kit for XM-3401B Internal CD-ROM Drive  | Err:511               |
| <b>3401-PS2 KIT</b>   | PS/2 (MCA-bus) Kit for TXM-3401E External CD-ROM Drive   | Err:511               |
| <b>3401-PS2-B KIT</b> | PS/2 (MCA-bus) Kit for XM-3401B Internal CD-ROM Drive  | Err:511               |
| <b>PA2113</b>         | 150-pin SCSI-2 Adapter (T2200SX/T3300SL/T4400 Series/T4500 Series/T4600 Series/T4700CT/T6400 Series)   | Err:511               |
| <b>CAD-01</b>         | Additional Disc Caddy (Single unit)  | Err:511               |
| <b>NOTE:</b>          | Microsoft Extensions software is included with PC and PS/2 kits and Toshiba kits.<br><br>Toshiba CD-ROM Drives support the "High Sierra" and "ISO 9660" standards. |                       |

**SMARTDRIVES**

| <b>PRODUCT #</b> | <b>DESCRIPTION</b>                                    | <b>CDN LIST PRICE</b> |
|------------------|---|-----------------------|
| <b>SMT-DRV</b>   | Toshiba Smart Drive (for T6400 Series)                | Err:511               |
| <b>CZ-3A08</b>   | Toshiba Smart Card                                    | Err:511               |
| <b>SMT-SDK</b>   | Software Development Kit (Microsoft C Libraries Only) | Err:511               |



**PRINTER SUPPLIES**

| <b>PRODUCT #</b> | <b>DESCRIPTION</b>                                  | <b>CDN LIST PRICE</b> |
|------------------|---|-----------------------|
| <b>PA2751</b>    | P201 Thermal Ribbon                                 | Err:511               |
| <i>PA8760</i>    | <i>P301 Thermal Ribbon (1 Box = 2 Ribbons)</i>      | <i>Err:511</i>        |
| <i>R21</i>       | <i>P321SL/P341SL Black Fabric Ribbon (1 Ribbon)</i> | <i>Err:511</i>        |
| <i>R31</i>       | <i>P351SX Black Fabric Ribbon (1 Ribbon)</i>        | <i>Err:511</i>        |
| <i>R41</i>       | <i>P311 Black Fabric Ribbon (1 Ribbon)</i>          | <i>Err:511</i>        |
| <i>RC11</i>      | <i>P351C Black Fabric Ribbon (1 Ribbon)</i>         | <i>Err:511</i>        |

**PRINTER ACCESSORIES**

| <b>PRODUCT #</b> | <b>DESCRIPTION</b> | <b>CDN LIST PRICE</b> |
|------------------|--------------------|-----------------------|
| <b>PA2402U</b>   | P201 Battery       | Err:511               |

**LASER PRINTER SUPPLIES**

| <b>PRODUCT #</b>  | <b>DESCRIPTION</b>                                 | <b>CDN LIST PRICE</b> |
|-------------------|--|-----------------------|
| <b>T-L401-C</b>   | Toner Cartridge for PL6 & PL8                      | Err:511               |
| <b>S-L401-10K</b> | Drum Kit (10,000 pages) for PL6 & PL8              | Err:511               |
| <b>OD-L200-C</b>  | Drum Cartridge (25,000 pages) for PL12             | Err:511               |
| <b>T-L200-C</b>   | Toner Cartridge (5,000 pages - 6 bottles) for PL12 | Err:511               |
| <b>S-L200-40K</b> | Developer Kit (40,000 pages) for PL12              | Err:511               |
| <b>HR-L200-C</b>  | Fuser (80,000 pages) for PL12                      | Err:511               |

Toshiba of Canada Limited - Information Systems Group

PRODUCT

T1900/120

PRODUCT

T1900C/200

PRODUCT

T1950/200

PRODUCT

T1950CS/200

PRODUCT

T1950CT/320

PRODUCT

T3400/120

PRODUCT

T3400CT/120

PRODUCT

T4500/200

PRODUCT

T4500C/200

PRODUCT

T4600/200

PRODUCT

T4600C/200

PRODUCT

T4600C/320

PRODUCT

T4700CT/320

PRODUCT

T6600C/510

PRODUCT

FC-T1900/120

PRODUCT

FC-T1900C/200

PRODUCT

FC-T1950/200

PRODUCT

FC-T1950CS/200

PRODUCT

FC-T1950CT/320

PRODUCT

FC-T3400/120

PRODUCT

FC-T3400CT/120

PRODUCT

*FC-T4500/200*

PRODUCT

*FC-T4500C/200*

PRODUCT

*FC-T4600/200*

PRODUCT

FC-T4600C/200

PRODUCT

FC-T4600C/320

PRODUCT

FC-T4700CT/320

PRODUCT

FC-T6600C/510

PRODUCT

*FC-T1800-U*

PRODUCT

FC-T1900-U

PRODUCT

FC-T1950-U

PRODUCT

FC-T3400-U

PRODUCT

*FC-T4400SX-U*

PRODUCT

FC-T4500-U

PRODUCT

FC-T4600-U

PRODUCT

FC-T4700-U

PRODUCT

*FC-T6400-U*

PRODUCT

*FC-T6600-U*

FR00001

PA2000U  
FR00001

PA2001U  
FR00001

PA2002U  
FR00001

PA2003U  
FR00001

PA2004U  
FR00001

PA2005U  
FR00001

PA2006U  
FR00001

PA2007U  
FR00001

PA2008U  
FR00001

PA2009U  
FR00001

PA2010U  
FR00001

PA2012U  
FR00001

PA2013U  
FR00001

PA2014U  
FR00001

PA2019U  
FR00001

PA2020U  
FR00001

PA2021U  
FR00001

PA7134  
FR00001

PA8311  
FR00001

PA8312  
FR00001

PA8314  
FR00001

PA7139  
FR00001

PA8306  
FR00001

PA8316  
FR00001

PA7137  
FR00001

PA8307  
FR00001

PA8301

PRODUCT

T24M

PRODUCT

BC2400M

PRODUCT

BC7520

PRODUCT

BC7521

PRODUCT

BC7522

PRODUCT

BC7523

PRODUCT

BC7530

PRODUCT

BC7564

PRODUCT

BC7566

PRODUCT

PA8723

PRODUCT

BC7501

PRODUCT

BC7506

PRODUCT

PA2404U  
PRODUCT

PA2407U  
PRODUCT

PA2410U  
PRODUCT

PA2412U  
PRODUCT

PA2413U  
PRODUCT

PA2420U  
PRODUCT

PA2422U  
PRODUCT

PA2481U  
PRODUCT

PA2482U  
PRODUCT

PA8712  
PRODUCT

PA8719  
PRODUCT

PA7490  
PRODUCT

PA7491  
PRODUCT

PA8715  
PRODUCT

PA2403  
PRODUCT

PA8725  
PRODUCT

PA8707  
PRODUCT

PA8708

PRODUCT

PA2701U

PRODUCT

PA2703U  
PRODUCT

PA2113

PRODUCT

PA-510L  
PRODUCT

PA8380  
PRODUCT

PA8601

Toshiba of Canada Limited - Information Systems Group

PRODUCT

PA2400U  
PRODUCT

PA2408U  
PRODUCT

PA2409U  
PRODUCT

PA2411U  
PRODUCT

PA2417U  
PRODUCT

PA2426U  
PRODUCT

PA2478U  
PRODUCT

PA7483  
PRODUCT

PA8701  
PRODUCT

PA8706  
PRODUCT

PA7485  
PRODUCT

PA7487  
PRODUCT

PA8727  
PRODUCT

PA8709

PRODUCT

PA2803U  
PRODUCT

PA7354

PRODUCT

PA8718

PRODUCT

PA8380  
PRODUCT

PA2800U

*PRODUCT*  
*XM-3401B-S*

*PRODUCT*  
*TXM-3401E*

*PRODUCT*  
*3401-PCF KIT*  
*PRODUCT*  
*3401-PCF-B KIT*  
*PRODUCT*  
*3401-PS2-600 KIT*  
*PRODUCT*  
*3401-PS2-600-B KIT*  
*PRODUCT*  
PA2113

*PRODUCT*  
CAD-01

*PRODUCT*  
SMT-DRV  
*PRODUCT*  
CZ-3A08  
*PRODUCT*  
SMT-SDK



PRODUCT

PA2751

PRODUCT

PA8760

PRODUCT

R21

PRODUCT

R31

PRODUCT

R41

PRODUCT

RC11

PRODUCT

PA2402U

PRODUCT

T-L401-C

PRODUCT

S-L401-10K

PRODUCT

OD-L200-C

PRODUCT

T-L200-C

PRODUCT

S-L200-40K

PRODUCT

HR-L200-C