



DPSD BIOS ENGINEERING

Intel Corporation, 5200 NE Elam Young Parkway
Hillsboro, OR 97124-6497

DATE: June 15, 2003
PRODUCT: Intel® D865PERL Desktop Board Standard BIOS

P07-0056 (Production 07, build 0056)

About This Release:

- 05-20-2003
- Core Baseline version 01.03.00
- RL86510A.86A.0056.P07.0305201221
- UNDI 4.1.10
- LAN UNDI 1.2.10

New Fixes/Features:

- Added CORE support for manual PCI IRQ routing.
- Lowered power consumption of Gigabit LAN when system is in S5.
- Fixed the issue, where some boards hanging at POST code 20h when CMOS battery is re-installed or at first power-up.
- Fixed boot block recovery failure during BIOS flash update with HT processor.
- Fixed issue where Windows XP legacy-to-native IDE runtime mode switching was not functioning.
- Added CKE workaround for enhanced S3 robustness.
- Correct fan monitoring text and fan speed RPM display.
- Added Audio progress indicator for BIOS updates. An increasing scale of beep tones are now emitted during BIOS updates.

P06-0052 (Production 06, build 0052)

About This Release:

- 05-02-2003
- Core Baseline version 01.03.00
- RL86510A.86A.0052.P06.0305020834
- UNDI 4.1.10
- Intel® 82547EI UNDI 1.2.10

New Fixes/Features:

- Fixed BIOS Hardware Health Monitor fan speed display.
- Capitalized RAID in the RAID setup option.
- Add "Additional System Information" in BIOS Setup Menu.
- Added Grayscale JPEG image support. Also added more robust error handling in JPEG decoder.
- Added processor support.
- Fix for the Backup block string being intact when the power fails during the middle of an erase cycle.
- Fixed boot to USB Zip media when USB Zip was emulated as Floppy and the actual format of Zip media was HDD.
- Added codes to hide Intel(R) RAID Technology setup option if ICH5-R is not present.

P05-0050 (Production 05, build 0050)

About This Release:

- 04-22-2003
- Core Baseline version 01.03.00
- RL86510A.86A.0048.P04.0304091908
- UNDI 4.1.10
- Intel® 82547EI UNDI 1.2.10

New Fixes/Features:

- Banner change to P05-0050
- Updated BIOS support code for Intel® Pentium® 4 processor with 800MHz system bus.
- Updated DPSD small Logo.
- Fixed false memory test post time error message when no failures and when dual channel optimization message needs to appear.
- Fixed WOL from S5 issue with Intel® 82547EI LAN.
- Added support for SKU with Intel Flex-6 audio and 10/100 Mbit/sec LAN subsystem.
- Fixed intermittent hang at post 2A issue and fixed LAN disable issue on some SKUs.
- Added support for Express BIOS Update 2.0.
- Fixed the problem where runtime GPNV Logo enable/disable feature.
- Added Adobe* Photoshop* JPEG image support and Microsoft* Windows* XP sample JPEG image support.
- Fixed issue where when the floppy disabled in Setup the system still booted to the floppy after exiting/escaping the BBS Popup Menu.
- Corrected ACPI S4 Sleep Type register value.
- Updated new System Configuration data

P04-0048 (Production 04, build 0048)

About This Release:

- 04-10-2003
- Core Baseline version 01.03.00
- RL86510A.86A.0048.P04.0304091908
- UNDI 4.1.10
- Intel® 82547EI UNDI 1.2.10

New Fixes/Features:

- Initial Production Release