

Area Fill.

This part of the Print Quality plot tries to:

- Check the print quality when printing area fills (CAD 3D and LFP).
- Show the ink media interactions.
- Validate the media and print quality settings.
- Set the optimal Lightness.

