

Intel Software: Intel® Application Accelerator 1.1 Production Version Release Notes

September 10, 2001

Microsoft Windows* 98*
Microsoft Windows 98 Second Edition
Microsoft Windows Millennium Edition
Microsoft Windows NT 4.0 (Service Pack 3.0+)
Microsoft Windows 2000 Professional

DISCLAIMER: Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty relating to sale and/or use of Intel products, including liability or warranties relating to fitness for a particular purpose, merchantability or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, lifesaving, or life-sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

* Other names and brands may be claimed as the property of others.

Copyright © Intel Corporation 2000-2001

Revision History

Date	Driver Revision	Build Number	Draft/Changes
September 6, 2001	1.1 Production Version	2053	Digitally signed CAT files included.

New Features

Features Added in 1.1		
Release Name	Description	Operating System
1.1 Production Version	N/A	N/A

Issues Resolved

Issues Resolved After Intel® Ultra ATA Storage Driver v6.10.011		
Reference No:	Description	Operating Systems
963203	Event Viewer message 'The request is incorrectly formatted for \Device\Ide\IntelAta0'	Windows* 2000
957609	'Report.txt' duplicates English text section on some systems.	Windows 2000
749484	Unable to play audio content from CDs in digital mode.	Windows 98 Windows 98 Second Edition Windows Millenium Edition
963536	System cannot locate Diablo* II CD, even with disk in CD-ROM drive.	Windows 2000
966220	Tribes* 2 exits to desktop without an error.	Windows 2000

Components Contained in this Release

Components Contained in 1.1 Production Version - Build 2053		
Component	Filename	Version
Windows* 2000 Driver	IdeChnDr.SYS	7.0.2035
Windows 98/SE/Me Driver	IntelATA.MPD	7.0.2017
Windows 98/SE/Me SMART VSD Driver	IntelVSD.VXD	7.0.2017
Windows NT 4.0 Driver	IntelATA.SYS	7.0.2017
Intel® Application Accelerator	IntelATA.EXE	1.1.2035