



# ES9528/ES9528-XT

## Firmware History (1800388)

---

### Changes from v1.4 to v1.4a

- Update web interface with a signed JAR file so that Java 7/Update 51 permits the web interface to open.using the Java default security settings.

### Changes in v1.4

- Fixed NetVision discovery bug
- Fixed IGMP IP subnet mask check
- Fixed web reboot bug
- EtherType help/storm control disabled
- VLAN max = 256
- Web save messaged changed
- Added DHCP server features
  - Option 82
  - DHCP Server assign IP address by Option82 content
  - DHCP Relay Agent can assign Circuit-ID and Remote-ID
  - DHCP Server assign IP address by Port
  - Port-based IP address assignment
- Added DHCP Relay Agent w/ Option 82 feature - Remote-ID can be specified by
  - MAC address
  - IP address
  - Arbitrary strings
- Added IPv6 address support
- Added enable/disable access to the switch via HTTP and Telnet
- Added Web save function
- Added new functions for NetVision
  - Password function
  - Gateway function
  - DHCP function
- Modified SSL Certificate Name

