<u>Supported Systems Software: 7.5.3</u> <u>SCSI: DB-25</u> <u>Serial Ports: 2</u> <u>Sound Output: 16-bit stereo 44.1 KHz sample rate</u> <u>ADB: 1, plus additional port for PS/2 keyboard</u> <u>Ethernet: Add-in card</u> <u>Machine Gestalt ID: ???</u>

## <u>Minutiae:</u>

Improve performance by installing a Newer Technology level-2 cache DIMM, part # 7CC512C.

<u>StarMax can take only 3.3 volt EDO DIMMs. It does not support</u> <u>interleaved memory. The three DIMM sockets are NOT identical.</u> <u>The first socket can only accept up to 32 MB DIMMs. The other two</u> <u>sockets can accept up to 64 MB DIMMs. The maximum memory is</u> therefore 160 MB.

<u>Manufactured by:</u> <u>Motorola Computer Group</u> <u>1-800-759-1107</u> <u>http://www.mot.com/computer/starmax</u>