

Sheet1

ID,C,22	COMMON,C,22	ADAPTER,C	PRIMAFCTYPE,C,18	VIDEO,C,18	
0000068024670004	PC #2 in Lab 'A'	Token-Ring	Enrico	COMPAQ 286 DP	HERCULES COLOR

Sheet1

MONITOR,C,18 PRINT1,C,18 PRINT2,C,18 SPCTYPE,C,SVIDEO,C,18 SMONITOR,CSPRINT1,C,18
NEC MULTISYNC 45876332-A

Sheet1

SPRINT2,C,1{	OPT1,C,14	OPT2,C,14	OPT3,C,14	OPT4,C,14	OPT5,C,14	OPT6,C,14	DR\DR\
Hayes 1200	Hercules co	above board					A: C:

Sheet1

DRV3ID,C,4	DRV4ID,C,4	DRV1TY	DRV2	DRV3TYPE,C	DRV4TYPE,C	DRV1\$	DRV2\$	DRV3SIZE,C,4
		Floppy	Hard			360K	20 M	

Sheet1

DRV4SIZE,C,IBAS_MEXT_MOS,C,10	NOTES1,C,68	NOTES2,C,68
640 K 1.5 M DOS 3.2	Network adapter board had a bad connector.	Repaired 10/15/86

NOTES3,C,68NOTES4,C,68ENT_COMMON,L
###