NEXTSTEP for Intel Processors Release 3.3

Networking Driver Overview

Driver: Intel 82596 Network

Driver Overview: NeXTanswer #1750

Last Update: March 25, 1996

Availability Information

Newer Released Driver in NeXTanswers: Yes, Version 3.33, as NeXTanswer #1749

Newer Beta Driver in NeXTanswers: No, Version 0.00, as NeXTanswer #

Driver Name / Installer .pkg: Intel82596NetworkDriver

Driver Type: Networking

Driver Scope: Specific Product

Supported Components: Intel i82596

PC Bus / Interface Supported by Driver*: EISA, PCI

General Overview notes: This driver supports adapters based on the Intel 82596 chipset.

Supported Products / Add-on Adapters:

Intel EtherExpress PRO/10 PCI (PILA8400) (BNC, UTP, AUI)

Intel EtherExpress PRO/10 PCI (PILA8420) (UTP)

Intel EtherExpress Flash32 EISA (EILA8225) (BNC, UTP, AUI)

Cogent eMaster EM935 EISA XL (BNC, UTP, AUI)

Cogent eMaster EM932 EISA (UTP, AUI)

Cogent eMaster EM932 EISA (BNC, UTP, AUI)

Cogent eMaster EM945 EISA FDE (BNC, UTP, AUI)

Supported Products / Systems (ie integrated into PC System):

Special Features of Driver / Driver Notes:

This driver obsoletes CogentEMaster

This device driver provides information in the Configure application's help panel. Choose Info>Help from the Configure menu and scroll down to find this device driver's help topic.

Networking Driver Details

Network Type*: EtherNet

Speed*: 10 Mb/s

Access Mode*: Bus Master DMA

Buffer Size*: N/A

Supported Connectors*: AUI, BNC, UTP

Known Problems

More than one instance of the adapter is autodetected in Configure.app. The full-duplex feature of the Cogent EM945 FDE adapter was not tested.

Driver Version Notes

3.31 - First release of this driver

3.33 - Added support for EE PRO/10 PCI

Future Planning

Future / Update Planning:

Reason for New Driver / Update:

New Driver / Update Timeframe:

New Driver / Update Description:

Note: Information contained in the "Future Planning" section of this document does not constitute a commitment on the part of NeXT to complete the planned development work.

* - Indicates information that is inclusive of the entire capability of this driver. Not all devices supported by this driver may include all features listed. Check any available NeXTanswers and the hardware manual for the device for additional information.

Product Vendor

Intel

- +1 (800) 628 8686 USA toll-free (customer service) phone
- +1 (916) 356 3600 bulletin board system (OEM components)
- +1 (800) 897 2536 USA toll-free bulletin board system (OEM components), viewing only
- +1 (800) 628 2283 faxback system (OEM components)
- +1 (503) 645 6275 bulletin board system (reseller information)
- +1 (800) 525 3019 USA toll-free bulletin board system
 - (reseller information), viewing only
- +1 (916) 356 3105 faxback system (reseller information)
- +1 (916) 356 6100 fax (customer support)

WWW: http://www.intel.com/