

NEXTSTEP for Intel Processors Release 3.3

Networking Driver Overview

Driver: HP Vectra XM, XP Integrated

Driver Overview: NeXTanswer #1786

Last Update: March 25, 1996

Availability Information

A version of this driver is on the CDROM

Newer Released Driver in NeXTanswers: No, Version 0.00, as NeXTanswer #

Newer Beta Driver in NeXTanswers: No, Version 0.00, as NeXTanswer #

Driver Name / Installer .pkg: HPVectra_XM_XP_LAN

Driver Type: Networking

Driver Scope: Specific Product

Supported Components: AMD Am79C960

PC Bus / Interface Supported by Driver*: Integrated

General Overview notes: This driver is only for the HP XM and XP Vectra series of computers. The Am79C960 is the ISA-based Ethernet controller used for the onboard Ethernet hardware in the HP Vectra XM and XP series of computers.

Supported Products / Add-on Adapters:

Supported Products / Systems (ie integrated into PC System):

HP Vectra XM

HP Vectra XP

Elonex WS4100 - Not tested, should work

Special Features of Driver / Driver Notes:

Networking Driver Details

Network Type*: EtherNet
Speed*: 10 Mb/s
Access Mode*: DMA
Buffer Size*: N/A
Supported Connectors*: BNC, UTP

Known Problems

This driver exhibits a problem where performance steadily degrades with use. This problem is currently under investigation by NeXT.

Driver Version Notes

Future Planning

Future / Update Planning:
Reason for New Driver / Update:
New Driver / Update Timeframe:

New Driver / Update Description:

Note: Information contained in the "Future Planning" section of this document does not constitute a commitment on the part of NeXT to complete the planned development work.

* - Indicates information that is inclusive of the entire capability of this driver. Not all devices supported by this driver may include all features listed. Check any available NeXTanswers and the hardware manual for the device for additional information.

Product Vendor

Hewlett Packard
3000 Hanover St.
Palo Alto, CA 94304
USA

+1 (800) 752-0900 USA toll-free phone
+1 (415) 857 1501 international phone
+1 (800) 333 1917 faxback system
+1 (408) 553 3500 bulletin board system
+1 (415) 857 5518 fax
WWW: <http://www.hp.com/>