# **NEXTSTEP for Intel Processors Release 3.3**

## **Display Driver Overview**

**Driver: HP Vectra XP** 

**Driver Overview:** NeXTanswer #1787

Last Update: March 25, 1996

## **Availability Information**

A version of this driver is on the CDROM

Newer Released Driver in NeXTanswers: No, Version 0.00, as NeXTanswer # Newer Beta Driver in NeXTanswers: No, Version 0.00, as NeXTanswer #

Driver Name / Installer .pkg: HPXPDisplayDriver

**Driver Type:** Display

**Driver Scope:** Specific Product

**Supported Components:** S3 928P, TI TVP3020 RAMDAC **PC Bus / Interface Supported by Driver\*:** Integrated

**General Overview notes:** This graphics driver is designed to support the on-board graphics controller of the Hewlett Packard Vectra XP series. The on-board graphics controller is based on the S3-928 chipset and can support 2MB or 4MB of VRAM.

### **Supported Products / Add-on Adapters:**

### Supported Products / Systems (ie integrated into PC System):

HP Vectra XP (4MB VRAM)

HP Vectra XP (2MB VRAM)

#### **Special Features of Driver / Driver Notes:**

## **Display Driver Details**

**Supported Connectors:** 15-pin High Density (VGA)

Access Mode: Linear Framebuffer

Adapter Memory: 2MB VRAM, 4MB VRAM

Display Modes (Number in () after resolution indicates frame buffer size required)

#### 32 Bit Color Modes\*:

1024x768 (4MB+), 640x480 (2MB+), 800x600 (2MB+)

#### 16 Bit Color Modes\*:

1024x768 (2MB+), 1152x819 (2MB+), 1280x1024 (2MB+), 800x600 (1MB+)

#### 8 Bit Color / Greyscale Modes\*:

1024x768 (1MB+), 1152X819 (1MB+), 1280x1024 (2MB+), 1600x1200 (2MB+), 800x600 (1MB+)

**Known Problems** 

**Driver Version Notes** 

## **Future Planning**

**Future / Update Planning:** 

Reason for New Driver / Update:

**New Driver / Update Timeframe:** 

**New Driver / Update Description:** 

**Note:** Information contained in the "Future Planning" section of this document does not constitute a commitment on the part of NeXT to complete the planned development work.

\* - Indicates information that is inclusive of the entire capability of this driver. Not all devices supported by this driver may include all features listed. Check any available NeXTanswers and the hardware manual for the device for additional information.

## **Product Vendor**

Hewlett Packard 3000 Hanover St. Palo Alto, CA 94304 USA

- +1 (800) 752-0900 USA toll-free phone
- +1 (415) 857 1501 international phone
- +1 (800) 333 1917 faxback system
- +1 (408) 553 3500 bulletin board system
- +1 (415) 857 5518 fax

WWW: http://www.hp.com/