NEXTSTEP for Intel Processors Release 3.3

Networking Driver Overview

Driver: Intel TokenExpress

Driver Overview: NeXTanswer #1793

Last Update: March 25, 1996

Availability Information

A version of this driver is on the CDROM

Newer Released Driver in NeXTanswers: No, Version 0.00, as NeXTanswer #

Newer Beta Driver in NeXTanswers: No, Version 0.00, as NeXTanswer #

Driver Name / Installer .pkg: TokenExpress

Driver Type: Networking

Driver Scope: Product Family

Supported Components:

PC Bus / Interface Supported by Driver*: ISA

General Overview notes: This adapter is not recommended for use with NEXTSTEP. New token ring installations should use the IBM Auto 16/4 Token Ring Adapter. See NeXTAnswer #1788 IBM Token Ring Driver Overview.rtf.

Supported Products / Add-on Adapters:

Supported Products / Systems (ie integrated into PC System):

Special Features of Driver / Driver Notes:

Networking Driver Details

Network Type*: Token Ring Speed*: 16 Mb/s, 4 Mb/s

Access Mode*: Buffer Size*:

Supported Connectors*: STP

Known Problems

This driver has been removed from future versions of NEXTSTEP.

Driver Version Notes

Future Planning

Future / Update Planning: Obsolete Reason for New Driver / Update: New Driver / Update Timeframe:

New Driver / Update Description:

Note: Information contained in the "Future Planning" section of this document does not constitute a commitment on the part of NeXT to complete the planned development work.

* - Indicates information that is inclusive of the entire capability of this driver. Not all devices supported by this driver may include all features listed. Check any available NeXTanswers and the hardware manual for the device for additional information.

Product Vendor

Intel

+1 (800) 628 8686 USA toll-free (customer service) phone

- +1 (916) 356 3600 bulletin board system (OEM components)
- +1 (800) 897 2536 USA toll-free bulletin board system (OEM components), viewing only
- +1 (800) 628 2283 faxback system (OEM components)
- +1 (503) 645 6275 bulletin board system (reseller information)
- +1 (800) 525 3019 USA toll-free bulletin board system
 - (reseller information), viewing only
- +1 (916) 356 3105 faxback system (reseller information)
- +1 (916) 356 6100 fax (customer support)

WWW: http://www.intel.com/