

Sheet1

MAKE,C,25	MODEL,C,1(FWCAESP,C,1	MEMCKEYBOARD,PS,C,15	FLOPPY1,C,15
Packard Bell	PB686	1024 PB5339KB	PB686PS MF504b-318u
Packard Bell	PB300	2048 PS/2-KBX	PB31PS JU-257-343P
	x x	640 PB58KB	PB58PS MF501B-318U
PACKARD BE	PB500	8 NONE	XFORMER NONE
PANASONIC	KX-P1124	8 NONE	XFORMER NONE
PANASONIC	KX-P1123	8 NONE	XFORMER NONE
PANASONIC	KX-P1124I		

Sheet1

FLOPPY2,C,15	HD,C,15	VIDEO,C,15	MB,C,15	HDCTRL,C,1
JU-157-243	ST-157/WD93044A	PBVGA/MULTI	PB686MB	WDAT-240
MF-504B-318U	ST-137A/ST-3120	ON BOARD	30016-MB	ON BOARD
NONE	ST-250R/ST-157R	PBEGA	PB58MB	ST-11R
NONE	NONE	NONE	PJWP1P1124M	
NONE	NONE	NONE	PJWP1P1123M	NONE
NONE	NONE	NONE	PJWP1P1124IM	NONE

Sheet1

COMMENT,C,70

Only upgradable to 1meg on mother board, can use memory card but you

SPEEDS 4.77/9.53 MHZ FARADAY VIDEO IC ST-250R DISCONTINUED

PRINT HEAD-PJWHP1124M RIBBON KX-P145

PRINT HEAD PJWHP1123M RIBBON KX-P145

PRINT HEAD-PJWHP1124IM RIBBON KX-P145

COMMENT1,C,70

need updated bios version 03D or higher, or you get intr. Memory

COMMEMEMOS,M

errors.