

<b>Institutional/Mfg.</b>		<b>Approximate installed cost \$ per sq. ft.*</b>	
<b>Applications</b>	<b>Product Name/Type</b>	<b>Low</b>	<b>High</b>
Office Area	VCT- Vinyl Composition Tile	\$1.00	\$2.70
	SVT - Solid Vinyl Tile	\$2.90	\$3.75
	LVT - Luxury Vinyl Tile	\$6.60	\$13.00
Break Area	VCT - Vinyl Composition Tile	\$1.00	\$2.70
	Series 8000 - Inlaid Commercial Sheet Vinyl	\$1.50	\$2.00
	SVT - Solid Vinyl Tile	\$2.90	\$3.75
	Linodom™ - Linoleum	\$3.25	\$4.00
Restroom-Non Shower Area	Series 8000 - Inlaid Commercial Sheet Vinyl	\$1.50	\$2.00
	Linodom™ - Linoleum	\$3.25	\$4.00
	Mipolam® - Homogeneous PVC Flooring	\$2.25	\$5.00
Executive Office	Series 8000 - Inlaid Commercial Sheet Vinyl	\$1.50	\$2.00
	Linodom™ - Linoleum	\$3.25	\$4.00
	LVT - Luxury Vinyl Tile	\$6.60	\$13.00
Computer Room	Series 8000 - Inlaid Commercial Sheet Vinyl	\$1.50	\$2.00
	Linodom™ - Linoleum	\$3.25	\$4.00
	Mipolam® 500 - Homogeneous PVC Flooring	\$3.50	\$5.00
Conference Room	Series 8000 - Inlaid Commercial Sheet Vinyl	\$1.50	\$2.00
	Linodom™ - Linoleum	\$3.25	\$4.00
	LVT - Luxury Vinyl Tile	\$6.60	\$13.00
Entrance Lobby	VCT- Vinyl Composition Tile	\$1.00	\$2.70
	SRVCT - Slip Resistant Vinyl Composition Tile	\$2.20	\$2.85
	SVT - Solid Vinyl Tile	\$2.90	\$3.75
	Linodom™ - Linoleum	\$3.25	\$4.00
	LVT - Luxury Vinyl Tile	\$6.60	\$13.00
Elevator	VCT- Vinyl Composition Tile	\$1.00	\$2.70
	SVT - Solid Vinyl Tile	\$2.90	\$3.75
	Linodom™ - Linoleum	\$3.25	\$4.00
	LVT - Luxury Vinyl Tile	\$6.60	\$13.00
Reception Area	Series 8000- Inlaid Commercial Sheet Vinyl	\$1.50	\$2.00
	SVT - Solid Vinyl Tile	\$2.90	\$3.75
	Linodom™ - Linoleum	\$3.25	\$4.00
	LVT - Luxury Vinyl Tile	\$6.60	\$13.00
Production Area	VCT- Vinyl Composition Tile	\$1.00	\$2.70
	Series 8000- Inlaid Commercial Sheet Vinyl	\$1.50	\$2.00
	Linodom™ - Linoleum	\$3.25	\$4.00
	Mipolam® - Homogeneous PVC Flooring	\$2.25	\$5.00

\* Approximate installed costs are for comparative purposes only. The ranges represent differences, taking in account specific products, encountered under various competitive job situations and do not include job conditions or subfloor preparation.