

Digital HiNote Windows 95 Customization

Your Digital HiNote has now been upgraded to Windows 95, congratulations! This program is designed to make some configuration changes to Windows 95 that will help optimize your new Operating System for your notebook computer. Due to the nature of Windows 95, these changes must be made manually, but they are fairly simple. You will be able to follow the instructions in this file at the same time you actually perform the changes. This will give you an idea of the types of new features found in Windows 95 and setup your HiNote at the same time. If you decide not to configure your system at this time, this file can be read anytime by running Wordpad (or any other text editor). Simply open the file a:\readme.txt on this diskette.

The Windows 95 settings that need to be changed are listed below. It is recommended that all four of these changes be made to optimize Windows 95 for your notebook computer. The exact steps to perform these changes are described below.

1. Color Setting - change from **16 colors** to **256 colors**
2. Display Type - change from **unknown display** to **Laptop Display Panel (640x480)**
3. File System - change from **Desktop Computer** to **Mobile or Docking System**
4. Port Com1 - change Bits per second from **9600** to **115200** (this change may also be applied to Com2 as applicable).

To read this file while actually performing the modifications, first make sure your printer is connected and set up, then use the Print command from the application you are using to view this file.

Changing the Color Setting and Display Type:

1. Click on the **Start** button in the lower left hand corner of the screen.
2. Move the pointer up to and click on the **Settings** selection on the menu.
3. Click on **Control Panel**.
4. Double click on the **Display** icon.
5. At the top of the screen, click on the **Settings** tab.
6. In the middle of the screen, under **Color palette**, click on the **down arrow** and then move the pointer to highlight the **256 Color** selection and click on it. **256 Color** will show in the box.
7. Next, click on **Change Display Type**, on the same screen near the bottom.
8. Under **Monitor Type**, click on the **Change** button
9. Highlight **Standard monitor types** in the left hand column
10. Highlight **Laptop Display Panel (640 x 480)** in the right hand column
11. Click on **OK** in the Select Device dialog box
12. Click on **Close** in the Change Display Type dialog box
13. Click on **OK** in the Display Properties dialog box
14. When prompted to restart Windows, answer **No**, the setup program will prompt for restarting when all modifications are completed.

Changing the File System and COM1 Speed settings:

1. Click on the **Start** button in the lower left hand corner of the screen.
2. Move the pointer up to the **Settings** selection on the menu.
3. Move the pointer right to the **Control Panel** selection and click on **Control Panel**.
4. Double click on the **System** icon at the bottom of the window
5. At the top of the screen, click on the **Performance** tab.
6. Near the bottom of the window on the left, click on **File System**.
7. Click on the down arrow next to the **Typical role of this machine** selection.
8. Move the pointer to **Mobile or docking System** and click on this option.

9. Click **OK** in the File System Properties dialog box.
10. Then select the **Device Manager** tab at the top of the System Properties dialog box
11. Find **Ports (COM & LPT)** near the bottom of the list and double click on it
12. Under **Ports (COM & LPT)** double click on **Communications Port (COM1)**
13. Click on the **Port Settings** tab at the top of the window
14. Click on the down arrow next to the **Bits per second** selection near the top of the window
15. Hilight the **115200** speed setting and click on it
16. Click **OK** at the bottom af the dialog box and **Close** in the next dialog box to return to Control Panel
15. When prompted to restart Windows, answer **No**, the setup program will prompt for restarting when all modifications are completed.

To continue with the Setup program, close the README.TXT window by clicking on the small box with the X in it in the upper right hand corner of the README.TXT window. This will complete the README section of the Setup program. You will then be asked to restart Windows 95. If you have made any changes you must restart Windows 95 at this point to make the changes active on your system.