

Sheet1

HERSTELLETYPEPENBEZ,C,UNF(FORM)STP SIZE,(HIGH)INTERICYLINHEAPREC(IBM)LEISBUFFFAU

Atasi	3036	0	30	0				0	0	0	0		
Atasi	3046	0	40	0				0	0	0	0		
BASF	6188	0	10	80	5.25	FH		0	0	0	0		
BASF	6188-R3	0	20	80				0	0	0	0		
CDC Wren	94355-100 S	0	76	17	3.5	1.6	MFM	1072	9	0	0		
CDC Wren 2	94155-48	0	42	28		?	MFM	925	5	0	0		
CDC Wren 2	94155-57	0	48	0	5.25	FH	MFM	925	6	0	0		
CDC Wren 2	94155-67	0	56	0	5.25	FH	MFM	925	7	0	0		
CDC Wren 2	94155-77	0	64	0	5.25	FH	MFM	925	8	0	0		
CDC Wren 2	94155-86	0	72	28	5.25	FH	MFM	925	9	0	0		
CDC Wren 3	?	0	95	16	5.25	HH	ESDI	0	0	0	0		
CDC Wren 3	94161	0	155	16	5.25	FH	ESDI	0	0	0	0		
CDC Wren 3	94166	0	155	16	5.25	FH	SCSI	0	0	0	0		
CDC Wren 5	94181	0	330	15			SCSI	0	0	0	0		
Conner	CP-2022	0	21	23	2.5	0.7	XT	635	2	0	2	8KB	T
Conner	CP-2024	0	21	23	2.5	0.7	AT	635	2	0	2	8KB	T
Conner	CP-30100	0	120	19	3.5	1.0	SCSI	1522	4	0	3	64KB	T
Conner	CP-30104	0	120	19	3.5	1.0	AT	1522	4	0	3	64KB	T
Conner	CP-30109	0	120	19	3.5	1.0	MCA	1522	4	0	3	64KB	T
Conner	CP-3020	0	21	27	3.5	1.0	SCSI	622	2	0	2	8KB	T
Conner	CP-3024	0	21	27	3.5	1.0	AT	615	4	0	2	8KB	T
Conner	CP-3040	0	40	25	3.5	1.0	SCSI	1026	2	0	2	8KB	T
Conner	CP-3044	0	43	25	3.5	1.0	AT	980	5	0	2	8KB	T
Conner	CP-3100	0	105	25	3.5	1.6	SCSI	776	8	0	3	16KB	T
Conner	CP-3104	0	105	25	3.5	1.6	AT	776	8	0	3	32KB	T
Conner	CP-3200F	0	213	16	3.5	1.6	SCSI	1366	8	0	4	64KB	
Conner	CP-3204F	0	213	16	3.5	1.6	AT	1366	8	0	4	64KB	T
Conner	CP-4024	0	22	29	3.5	0.8	AT	627	2	0	2	8KB	T
Conner	CP-4044	0	43	29	3.5	0.8	AT	1104	2	0	2	8KB	T
Epson	HMD-720	0	25	67	3.5	1.6		614	4	0	8	none	F
Fujitsu	M2227D2	0	40	35	3.5	1.6	MFM	615	8	none	0	0	
Fujitsu	M2241AS2	0	25	30	5.25	HH	FMF	754	4	none	0	0	
Fujitsu	M2242AS2	55	43	30	5.25	HH	MFM	754	7	none	26	0	
Fujitsu	M2243AS2	86	68	30	5.25	FH	MFM	754	11	none	27	18	T
Fujitsu	M2243R	0	111	25	5.25	HH	RLL	1186	7	none	0	18	T
Fujitsu	M2243T	86	68	25	5.25	HH	MFM	1186	7	none	0	18	T
Fujitsu	M2246E	0	141	25	5.25	FH	ESDI	823	10	0	30		
Fujitsu	M2246SA	0	141	25	5.25	FH	SCSI	823	10	0	32	16KB	
Fujitsu	M2249E	0	334	18	5.25	FH	ESDI	1243	15	0	38		
Fujitsu	M2249SA	0	334	18	5.25	FH	SCSI	1243	15	0	40	16KB	
Fujitsu	M2263SA	0	670	16			SCSI	0	0	0	0		
Fujitsu	M2266S/H	1266	955	15	5.25	FH	SCSI	1658	15	0	0		
Fujitsu	M2266SA/HB	1266	1082	15	5.25	FH	SCSI	1658	15	0	0		
Fujitsu	M2266SB/HB	1266	1140	15	5.25	FH	SCSI	1658	15	0	0		
Fujitsu	M2611S	0	45	25	3.5	1.0	SCSI	1334	2	0	9		
Fujitsu	M2611T	0	45	25	3.5	1.0	AT	1334	2	0	7		
Fujitsu	M2612S	108	90	25	3.5	1.6	SCSI	1334	4	0	10		
Fujitsu	M2612T	108	90	25	3.5	1.6	AT	1334	4	0	8		
Fujitsu	M2613S	162	135	25	3.5	1.6	SCSI	1334	6	0	10		
Fujitsu	M2613T	162	135	25	3.5	1.6	AT	1334	6	0	8		

MADE BEMERKUNG,C,21

== ST4806

== ST4182E

== ST4182N

== ST4385N

now 5V only
now 5V only
now
now also EISA
now
now
now
now
now < 40 dBA
now < 40 dBA
now < 40 dBA
now < 40 dBA
now 5V only
now 5V only
now >=40dBA

1989
1989
now
now
now
now
now 512 Bytes/Sector
now
now 512 Bytes/Sector
now 512 Bytes/Sector
now 256 Bytes/Sector
now 512 Bytes/Sector
now 1024 Bytes/Sector
now
now
now
now
now