

@ DLTEST-4 Left and Right Margin Commands

PPitch set to 10 cpi

0L...5...1...5...2...5...3...5...4...5...5...5...6...5...7...5...

lL for ESC 'l' 0

l¶L for ESC 'l' 20

l(L for ESC 'l' 40

l<L for ESC 'l' 60

l2L...5...1...5...2...5...3...5...4...5...5...5...6...5...7...5...

Pitch set to 16.66 cpi

0L...5...1...5...2...5...3...5...4...5...5...5...6...5...7...5...

lL for ESC 'l' 0

l¶L for ESC 'l' 20

l(L for ESC 'l' 40

l<L for ESC 'l' 60

l2L...5...1...5...2...5...3...5...4...5...5...5...6...5...7...5...

↑

Bypass code ESC ESC '&s0C' turns laser printer end-of-line wrap on

QARight margin set with ESC 'Q' 65

L...5...1...5...2...5...3...5...4...5...5...5...6...5...7...5...8

Q(Right margin set with ESC 'Q' 40

L...5...1...5...2...5...3...5...4...5...5...5...6...5...7...5...8

QPRight margin set with ESC 'Q' 80

L...5...1...5...2...5...3...5...4...5...5...5...6...5...7...5...8

L/R margins set with ESC 'X' 20 50X¶2

L...5...1...5...2...5...3...5...4...5...5...5...6...5...7...5...8

Bypass code ESC ESC 9 CR clears both margins on laser printer

XPDot matrix printer requires ESC 'X' 0 80 to reset

L...5...1...5...2...5...3...5...4...5...5...5...6...5...7...5...8

Bypass code ESC ESC '&s1C' turns laser printer end-of-line wrap off

QARight margin set with ESC 'Q' 65

L...5...1...5...2...5...3...5...4...5...5...5...6...5...7...5...8

Q(Right margin set with ESC 'Q' 40

L...5...1...5...2...5...3...5...4...5...5...5...6...5...7...5...8

QPRight margin set with ESC 'Q' 80

L...5...1...5...2...5...3...5...4...5...5...5...6...5...7...5...8

L/R margins set with ESC 'X' 20 50X¶2

L...5...1...5...2...5...3...5...4...5...5...5...6...5...7...5...8

XPDot matrix printer requires ESC 'X' 0 80 to reset

Bypass code ESC ESC 9 CR clears both margins on laser printer

L...5...1...5...2...5...3...5...4...5...5...5...6...5...7...5...8